Instructions for Preparing Files for Laser Cutting and Bending

For the optimal execution of your order, please send us a technical drawing (PDF) and correctly prepared files in (DXF, DWG, STEP) format with dimensions in mm and at a 1:1 scale.

Requirements for Laser Cutting:

- Cutting lines: solid lines.
- If engraving is required, it should be specifically marked.

Requirements for Laser Cutting and Bending:

- Include a technical drawing and a STEP file with bending data.

File Submission:

- Send your files to info@vija.si
- Specify the material type, thickness, quantity, and any special requirements.